#### Diversified Power, Inc. All Terrain Crane Condition Report

	Ins	pection Date	9/14/2010	Equipment #	MC1024		
Make: Krupp		Model: KMK	5090		1995		
Type of Equip.:	Telescoping Crane	S/N: 50908156					
Boom Length:	135'	Jib Length:		Hour Meter:			
		olo Longin.		riour meter.	1012		
Ratings are : Not Applicable, Excellent, Good,		Comments					
	ory, Fair, Poor						
Overall Appearance:	Satisfactory	Truck SN W0909D580NWK20156. Unit complete with aux winch, Nelson boom dolly, jib, and two extra counterweights.					
Operating Condition:	Satisfactory						
Engine	Crane engine	Note: Boom must be raised to tilt cab for chassis engine.					
Mfg:	Mercedes	Oil leaks at all injectors.					
Run/Start:	yes						
Oil Leaks:	Yes						
Batteries:	New						
Cooling System:	Satisfactory						
Transmission		Transmission	will not shift into reve	erse without swi	tching key switch.		
Condition:	see notes	]					
Туре:	4-speed auto						
Oil Leaks:	yes						
Machine		Left rear outriggers leaking oil. Middle axle brakes will not release properly. Major air leak at middle of carrier. Jumper wire has been installed in fuse box.					
Sheet Metal:	Satisfactory						
Paint:	Satisfactory						
Brakes:	See notes						
Drivetrain:	Satisfactory						
Steering:	Satisfactory						
Axle Steer:	yes	]					
Outriggers:	See notes						
Cab or OROPS	Cab		-	· · · · · · · · · · · · · · · · · · ·	eak at right joystick in		
Door:	Good		dditional toggle functi	on enable swite	ch has been added in		
Glass:	Good	upper cab.					
Seat:	Worn						
Air Conditioner:	No	]					
Heater:	Yes	7					
L M I System:							
Front Tires		1st axle @ 75% both					
Condition:	Satisfactory	2nd axle: Left 75% - Right 50% 3rd axle: Left 75% - Right 75%					
% Remaining:							
Tire Size:	525/80R25						

Condition Report Continued to Page 2.

#### Diversified Power, Inc. All Terrain Crane Condition Report

		Inspection Date	9/14/2010	Equipment #	MC1024			
Make: Krupp		Model: KMK	5090	Year	1995			
Type of Equip.:	Telescoping Crane	e		S/N	50908156			
Boom Length:	135'	Jib Length:	0	Hour Meter	4372			
Ratings are :								
Not Applicable, Excellent, Good,			Comments					
Average, Fair, Poor								
Rear Tires			4th axle: Left 75% - Right 75% (has metal rod in tire - see photo)					
Condition:	Satisfactory		5th axle: Left 75% - Right 50%					
% Remaining:		Truck equipp	Truck equipped w/ spare.					
Tire Size:	225/80R25		]					
Hydraulics		Hydraulic oil	Hydraulic oil leak behind 1st axle left side tire - see picture. Machine low					
Pumps:	Satisfactory	on hydraulic	on hydraulic fluid.					
Valves:	Satisfactory							
Lines:	Satisfactory							
Oil Leaks:	yes-see notes							
Boom		Boom extend	ls slowly.					
Condition:	Satisfactory							
Pins & Bushings:	Satisfactory		1 I					
Cylinders:	Satisfactory							
Winch		Block has no	data plate - cannot be	e certified.				
Winch Condition:	Satisfactory							
Cable Condition:	Satisfactory							
Block:	Satisfactory							
Ball:	Satisfactory							
Aux. Winch:	did not test							
Jib:	did not test							
Additional Comments:								



# Diversified Power, Inc. All Terrain Crane Condition Report



# Diversified Power, Inc. All Terrain Crane Condition Report



#### Diversified Power, Inc. All Terrain Crane Condition Report



# Diversified Power, Inc. All Terrain Crane Condition Report




# Diversified Power, Inc. All Terrain Crane Condition Report


	In	spection Date	1/0/1900	Equ	ipment #	MC1024
Make: 0		Model: 0			Year:	1995
Type of Equip.:	0				S/N:	1995
Boom Length:	Telescoping Crane	Jib Length:	0	Н	our Meter:	50908156
	ion contained in this prior to purchase. T	here is no warr		ss or implied and		

merchantability.


# Diversified Power, Inc. All Terrain Crane Condition Report




# Diversified Power, Inc. All Terrain Crane Condition Report




# Diversified Power, Inc. All Terrain Crane Condition Report



# Diversified Power, Inc. All Terrain Crane Condition Report




# Diversified Power, Inc. All Terrain Crane Condition Report



# Diversified Power, Inc. All Terrain Crane Condition Report



### Diversified Power, Inc. All Terrain Crane Condition Report



# Diversified Power, Inc. All Terrain Crane Condition Report



# Diversified Power, Inc. All Terrain Crane Condition Report










#### Diversified Power, Inc. All Terrain Crane Condition Report





# **Diversified Power, Inc.** All Terrain Crane Condition Report





The information contained in this report is informative only. It is recommended that you conduct your own inspection prior to purchase. There is no warranty, express or implied and no warranty of fitness or

merchantability.

#### Diversified Power, Inc. All Terrain Crane Condition Report





