		Inspection Date	4/17/2010	Equipment # MC948					
Make: ASV		Model SR8		Year:					
Type of Equip.	multi terrain load		1512	S/N: SEA00657					
Bucket Widths	72"	Pad Width:	20"	Attachments: N/A					
	N/A, Excellent, Good,	i ad Widtii.	20						
_	actory, Fair, Poor			Comments					
Overall Appearance:	Satisfactory	Unit has power	Unit has power quick attach for bucket and high flow hydraulics.						
Operating Condition:	Fair	See notes on	See notes on joystick.						
Engine		Cranks easily	, runs good.						
	Mfg: Perkins								
Run / St									
Oil Lea									
Batter									
Cooling System Hydraulic	em: Salistaciony		ystick functions	e eluggiehly					
Pum	Satisfactory		ystick fullctions	s sluggistily.					
Val	<u> </u>								
	es: Satisfactory								
Oil Lea									
Tracks		Sprocket bus	Sprocket bushings worn, front & rear idlers show some damage, bottom						
Rubi	ber: Fair	rollers fair and tracks have cuts (RH) and tears LH & RH.							
Sproc			<u> </u>						
Bushir									
Rolle									
	ller: Fair	10/							
Bucket		wear noted ii	n pins & bushii	ngs.					
Condition									
Cutting ed Pins & Bushin	<u> </u>								
Cyline	J - 1								
Boom			n pins & bushii	ngs.					
Condit	ion: Satisfactory			Ĭ					
Pins & Bushir									
Cylinde	ers: Satisfactory								
Machine			tches front and	d rear paint.					
Sheet Me									
	int: Fair								
	ard:	Face to 1.1	I A /O I	naturally assessment to the to the					
	Satisfactory		•	· · · · · · · · · · · · · · · · · · ·					
			auge does not	WOIK.					
_									
Hea									
Rear Gua Cab Do Gla S Air Condition	soor: Satisfactory sss: Satisfactory eat: Satisfactory Fair	tachometer g	olow, A/C does auge does not	not work, compressor belt noisy & work.					



The information contained in this report is informative only. It is recommended that you conduct your own inspection prior to purchase. There is no warranty, express or implied and no warranty of fitness or

PIN

ASY, Inc. A Caterpillar Affiliate 840 Lily Lane P.O. Box 5160

Grand Rapids, MN 55744 (218) 327-3434

merchantability.

 Inspection Date
 4/17/2010
 Equipment #
 MC948

 Make:
 ASV
 Model SR80
 Year: 0

 Type of Equip.
 multi terrain loader
 Hour Meter H





The information contained in this report is informative only. It is recommended that you conduct your own inspection prior to purchase. There is no warranty, express or implied and no warranty of fitness or merchantability.

Inspection Date 4/17/2010 Equipment # MC948

Make: ASV Model SR80 Year: 0

Type of Equip. multi terrain loader Hour Meter 1512 S/N: SEA00657



In			spection Date		4/17/2010		Equipment #		MC948
Make:	ASV		Model	SR80	0			Year:	0
Type of E	quip.	multi terrain loader	Hour M	eter	1512	S/N:	SEA0	0657	



			nspection Date		4/17/2010	E		uipment #	MC948	
Make:	ASV		Model	SR80)			Year:	0	
Type of Equip.		multi terrain loader	Hour Meter		1512	S/N:	SEA00657			



Inspection Date 4/17/2010 Equipment # MC948


Make: ASV Model SR80 Year: 0

Type of Equip. multi terrain loader Hour Meter 1512 S/N: SEA00657





Make:	ASV		Model S	Year: 0		
Type of Equip.		multi terrain loader	Hour Met	ter 1512	S/N: SEA0	0657





The information contained in this report is informative only. It is recommended that you conduct your own inspection prior to purchase. There is no warranty, express or implied and no warranty of fitness or merchantability.





The information contained in this report is informative only. It is recommended that you conduct your own inspection prior to purchase. There is no warranty, express or implied and no warranty of fitness or merchantability.