

## Diversified Power, Inc. Tower Crane Condition Report

	Inspection Date <b>9/14/2010</b>	Equipment # <b>MC1025</b>
Make: <b>Terex/Comedil</b>	Model: <b>CTL630-32</b>	Year: <b>2006</b>
Type of Equip.: <b>Tower Crane</b>		S/N: <b>G4806003</b>
Boom Length:	Jib Length:	Hour Meter:
<b>Ratings are :          Not Applicable, Excellent, Good,          Satisfactory, Fair, Poor</b>		<b>Comments</b>
Overall Appearance:	<b>Satisfactory</b>	Unit missing electrical cabling. Not able to verify if all accessories and components are on site / unit arrived disassembled.
Operating Condition:		
Engine		See photos.
<i>Mfg:</i>		
<i>Run:</i>		
<i>Oil Leaks:</i>		
<i>Batteries:</i>		
<i>Cooling System:</i>		
Transmission		
<i>Condition:</i>		
<i>Type:</i>		
<i>Oil Leaks:</i>		
Machine		
<i>Sheet Metal:</i>		
<i>Paint:</i>		
<i>Brakes:</i>		
<i>Drivetrain:</i>		
<i>Steering:</i>		
<i>Rear Axle Steer:</i>		
<i>Outriggers:</i>		
Cab or OROPS		
<i>Door:</i>		
<i>Glass:</i>		
<i>Seat:</i>		
<i>Air Conditioner:</i>		
<i>Heater:</i>		
<i>L M I System:</i>		
Front Tires		
<i>Condition:</i>		
<i>% Remaining:</i>		
<i>Tire Size:</i>		

Condition Report Continued to Page 2.

## Diversified Power, Inc. Tower Crane Condition Report

	Inspection Date <b>9/14/2010</b>	Equipment # <b>MC1025</b>
Make: <b>Terex/Comedil</b>	Model: <b>CTL630-32</b>	Year: <b>2006</b>
Type of Equip.: <b>Tower Crane</b>		S/N: <b>G4806003</b>
Boom Length: <b>0</b>	Jib Length: <b>0</b>	Hour Meter: <b>0</b>
<b>Ratings are :        Not Applicable, Excellent, Good,        Average, Fair, Poor</b>	<b>Comments</b>	
<b>Rear Tires</b>		
<i>Condition:</i>		
<i>% Remaining:</i>		
<i>Tire Size:</i>		
<b>Hydraulics</b>		
<i>Pumps:</i>		
<i>Valves:</i>		
<i>Lines:</i>		
<i>Oil Leaks:</i>		
<b>Boom</b>		
<i>Condition:</i>		
<i>Pins &amp; Bushings:</i>		
<i>Cylinders:</i>		
<b>Winch</b>		
<i>Winch Condition:</i>		
<i>Cable Condition:</i>		
<i>Block:</i>		
<i>Ball:</i>		
<i>Aux. Winch:</i>		
<i>Jib:</i>		
<b>Additional Comments:</b>		



The information contained in this report is informative only. It is recommended that you conduct your own inspection prior to purchase. There is no warranty, express or implied and no warranty of fitness or merchantability.

# Diversified Power, Inc. Tower Crane Condition Report

Inspection Date	9/14/2010	Equipment #	MC1025	
Make:	Terex/Comedil	Model:	CTL630-32	
Type of Equip.:	Tower Crane	Year:	2006	
Boom Length:	0	S/N:	G4806003	
	Jib Length:	0	Hour Meter:	0




The information contained in this report is informative only. It is recommended that you conduct your own inspection prior to purchase. There is no warranty, express or implied and no warranty of fitness or merchantability.

# Diversified Power, Inc.

## Tower Crane Condition Report

Inspection Date	9/14/2010	Equipment #	MC1025
Make:	Terex/Comedil	Model:	CTL630-32
Type of Equip.:	Tower Crane	Year:	2006
Boom Length:	0	S/N:	G4806003
Jib Length:	0	Hour Meter:	0




The information contained in this report is informative only. It is recommended that you conduct your own inspection prior to purchase. There is no warranty, express or implied and no warranty of fitness or merchantability.

# Diversified Power, Inc.

## Tower Crane Condition Report

Inspection Date	9/14/2010	Equipment #	MC1025
Make:	Terex/Comedil	Model:	CTL630-32
Type of Equip.:	Tower Crane	Year:	2006
Boom Length:	0	S/N:	G4806003
Jib Length:	0	Hour Meter:	0



The information contained in this report is informative only. It is recommended that you conduct your own inspection prior to purchase. There is no warranty, express or implied and no warranty of fitness or merchantability.

# Diversified Power, Inc.

## Tower Crane Condition Report

Inspection Date	9/14/2010	Equipment #	MC1025	
Make:	Terex/Comedil	Model:	CTL630-32	
Type of Equip.:	Tower Crane	Year:	2006	
Boom Length:	0	S/N:	G4806003	
	Jib Length:	0	Hour Meter:	0





The information contained in this report is informative only. It is recommended that you conduct your own inspection prior to purchase. There is no warranty, express or implied and no warranty of fitness or merchantability.

# Diversified Power, Inc.

## Tower Crane Condition Report

Inspection Date	9/14/2010	Equipment #	MC1025	
Make:	Terex/Comedil	Model:	CTL630-32	
Type of Equip.:	Tower Crane	Year:	2006	
Boom Length:	0	S/N:	G4806003	
	Jib Length:	0	Hour Meter:	0




The information contained in this report is informative only. It is recommended that you conduct your own inspection prior to purchase. There is no warranty, express or implied and no warranty of fitness or merchantability.

# Diversified Power, Inc.

## Tower Crane Condition Report


	Inspection Date <b>9/14/2010</b>	Equipment # <b>MC1025</b>
Make: <b>Terex/Comedil</b>	Model: <b>CTL630-32</b>	Year: <b>2006</b>
Type of Equip.: <b>Tower Crane</b>		S/N: <b>G4806003</b>
Boom Length: <b>0</b>	Jib Length: <b>0</b>	Hour Meter: <b>0</b>



The information contained in this report is informative only. It is recommended that you conduct your own inspection prior to purchase. There is no warranty, express or implied and no warranty of fitness or merchantability.



# Diversified Power, Inc. Tower Crane Condition Report



The information contained in this report is informative only. It is recommended that you conduct your own inspection prior to purchase. There is no warranty, express or implied and no warranty of fitness or merchantability.

## Diversified Power, Inc. Tower Crane Condition Report



The information contained in this report is informative only. It is recommended that you conduct your own inspection prior to purchase. There is no warranty, express or implied and no warranty of fitness or merchantability.

# Diversified Power, Inc. Tower Crane Condition Report



The information contained in this report is informative only. It is recommended that you conduct your own inspection prior to purchase. There is no warranty, express or implied and no warranty of fitness or merchantability.

# Diversified Power, Inc. Tower Crane Condition Report



The information contained in this report is informative only. It is recommended that you conduct your own inspection prior to purchase. There is no warranty, express or implied and no warranty of fitness or merchantability.

# Diversified Power, Inc. Tower Crane Condition Report




The information contained in this report is informative only. It is recommended that you conduct your own inspection prior to purchase. There is no warranty, express or implied and no warranty of fitness or merchantability.

# Diversified Power, Inc. Tower Crane Condition Report




The information contained in this report is informative only. It is recommended that you conduct your own inspection prior to purchase. There is no warranty, express or implied and no warranty of fitness or merchantability.

# Diversified Power, Inc. Tower Crane Condition Report



The information contained in this report is informative only. It is recommended that you conduct your own inspection prior to purchase. There is no warranty, express or implied and no warranty of fitness or merchantability.

# Diversified Power, Inc. Tower Crane Condition Report



The information contained in this report is informative only. It is recommended that you conduct your own inspection prior to purchase. There is no warranty, express or implied and no warranty of fitness or merchantability.



# Diversified Power, Inc. Tower Crane Condition Report



The information contained in this report is informative only. It is recommended that you conduct your own inspection prior to purchase. There is no warranty, express or implied and no warranty of fitness or merchantability.

## Diversified Power, Inc. Tower Crane Condition Report



The information contained in this report is informative only. It is recommended that you conduct your own inspection prior to purchase. There is no warranty, express or implied and no warranty of fitness or merchantability.

# Diversified Power, Inc. Tower Crane Condition Report



The information contained in this report is informative only. It is recommended that you conduct your own inspection prior to purchase. There is no warranty, express or implied and no warranty of fitness or merchantability.

# Diversified Power, Inc. Tower Crane Condition Report



The information contained in this report is informative only. It is recommended that you conduct your own inspection prior to purchase. There is no warranty, express or implied and no warranty of fitness or merchantability.

# Diversified Power, Inc. Tower Crane Condition Report



The information contained in this report is informative only. It is recommended that you conduct your own inspection prior to purchase. There is no warranty, express or implied and no warranty of fitness or merchantability.

# Diversified Power, Inc. Tower Crane Condition Report



The information contained in this report is informative only. It is recommended that you conduct your own inspection prior to purchase. There is no warranty, express or implied and no warranty of fitness or merchantability.

# Diversified Power, Inc. Tower Crane Condition Report



The information contained in this report is informative only. It is recommended that you conduct your own inspection prior to purchase. There is no warranty, express or implied and no warranty of fitness or merchantability.